12 EASY STEPS TO BOX PRINTING











Here are the basic steps when working with a printer.

- 1. Supply box sizes and colors. Do not waste their time giving pieces of info. They loose money and will drop your job.
- 2. They do not need any graphic files to make a bid. If they ask? That is a red flag of bull crap.
- 3. Rep sends back written estimate.
- 4. Approve estimate in writing.
- 5. Box engineer creates a mock up box for your approval and product testing. You must sign the box approval label and send the box back. Allow 5 days plus shipping.
- **6.** Die line is created. This die line is what we use to place all the graphics.
- 7. Ask for upload info or send print files via Hightail or WeTransfer. Note: Do not open our files or try. These are ai files. With important folders. If they get messed up. Not our problem.
- 8. Printer then sends you a COLOR e proof. Review carefully and send back written approval. Not the best time to make any changes. Printers will charge you over \$100 hour for any changes!
- 9. Allow 7 days for e-proofs.
- 10. Allow 6 weeks for printing and another 5 days for shipping. ***Unless you pay them for extra shipping costs.
- 11. Do not expect them to save the files. They do not.
- 12. Custom box die cost from \$275.00 \$950

Once you do it one time. It becomes easier. No matter who prints it.



425-513-8822

mronhansen.com